

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

IH1212  
NNE  
> 1  
1.577 mi.  
8327 ft.

MANHOLE 2529  
AVE S AND EAST 2ND ST  
BROOKLYN, NY

NY Spills S106970079  
N/A

Site 2 of 2 in cluster IH

Relative:  
Higher

Actual:  
23 ft.

SPILLS:

Name: MANHOLE 2529  
Address: AVE S AND EAST 2ND ST  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0505082 / 2006-01-10  
Facility ID: 0505082  
Facility Type: ER  
DER Facility ID: 296487  
Site ID: 350041  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2005-07-27  
Investigator: GDBREEN  
Referred To: Not reported  
Reported to Dept: 2005-07-27  
CID: 409  
Water Affected: Not reported  
Spill Source: Institutional, Educational, Gov., Other  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2005-07-27  
Spill Record Last Update: 2006-01-10  
Spiller Name: ERT DESK MIKE DAUGHTERY  
Spiller Company: MANHOLE 2529  
Spiller Address: AVE S/ EAST 2ND ST  
Spiller Company: 001  
Contact Name: ERT DESK MIKE DAUGHTERY  
DEC Memo: "160059. 7/27/05 04:22 HRS. ROCCO LaROCCO #76043, SR. FIELD OPERATOR WITH F.O.D., REPORTS WHILE ON LOCATION TO PLACE GROUNDS ON FEEDER 7B45 (ACCT C3242) AT 04:00 HRS. FOUND APPROX. 2 QTS. OF UNKNOWN OIL AND WET MUD ON CONCRETE FLOOR OF TM-2529. SPILL APPEARS TO BE CONTAINED. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. NO PRIVATE PROPERTY AFFECTED. NO FIRE OR SMOKE INVOLVED. ENV STOP TAG 40738 PLACED. LIQUID SAMPLE TAKEN ON E PRIORITY TURNAROUND. CHAIN OF CUSTODY FORM # DD-10594. 72-HOUR DEMININIS. CLEANUP PENDING PCB RESULTS. -- W. WAINWRIGHT #17344 -- 7/27/05 04:45 HRS. -- AS PER FEEDER CONTROL REP. J. FRANCO, BROOKLYN/QUEENS EQUIPMENT GROUP CONDEMNED TM-2529. UNIT BELOW MIN. UNDERGROUND TO INSTALL L.E.C. IN TM-2529. TRANSFORMER TO BE CHANGED ON ISOLATED. (LAYOUT E05-14136-B). -- W.W. #17344 -- Lab Sequence Number: 05-07712-001 MATRIX: OIL GRAB. TOTAL PCB 4 ppm. Update - 7/27/05 1400 hrs. Removing job from 72 hr clock as per D. Hearn. Unit will not be removed during the timeframe. Advised CIG R. Elliot @ 1405 hrs. cn#19661 "  
Remarks: "2 QUARTS. HAS NO BEEN CLEANED UP. TRANSFORMER NEEDS TO BE REMOVED AND CHANGED. NO TO FOUR QUESTIONS. CON ED# 160059"

All Materials:

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Site ID: 350041  
Operable Unit ID: 1107623  
Operable Unit: 01  
Material ID: 2097512  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 2.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported